

Report ID: 19,517,464 Version: 1 11 Jun 2019 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:	JWB963	Reg Expiry:	30 Aug 2019	Engine			
	31 May 2019	Odometer:	87,931 Kms	Good No:	19517464	Oil level	~		
VIN:	KL3CD2669GB510417	Next Service:		Service Histor		Smoke & fumes	~		
					,	Performance	~		
	port is not a warranty		~ · · ·			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SW	-0	SP SP		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s dla			the	EI SP	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+	SC	Clutch			~
P = pin dent						CV joints	~		•
* = decals	SPSC PIC			AL.		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P S S						Performance			
		Note: som	he defects & blemishes	may not be disp		Hand Brake	~		
	pection Comments		le delects & blemisnes	indy not be disp	ayed in the diagram		•	oftyre	) )
RH wing mirror indicator lens cracked Rear bumper misaligned. Front bumper grille cracked						Tyres (lowest observed tread depth of tyres)   Left front 4			
LH headlamp low beam not working							4		mm
						Right front Left rear		2	mm
							1		mm
Conditions During Body Inspection: Dry						Right rear	2 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
4WD	inage a onder bor	meenspeede	<u>eonnents</u>			Suspension			
400						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights		~	
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	-		~
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timing (				Remote locking	~		
-	of Cam Belt Replac	-		Kms:		Sat. Nav. (basic test only)			~
Lvidence	огсант вен керіас	ement. N	lot Applicable	1/112.		Reversing camera	~		
Inspected by: Mathew Varghese Date: 11 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....