

Basic Vehicle Condition Guide

Report ID: 19,517,591


Version: 3

04 Jul 2019 Created:

Make: Model: Mazda Atenza **Body Style:** Sedan Year: 2012 Registration: KRB290 Reg Expiry: 25 Dec 2019 WoF Expiry: **Odometer:** 17 Jul 2020 92,063 Kms **Good No:** 19517591 VIN: 7AT0C139X17203425 **Next Service:** 102000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Tidy.

| Interior Comments | 1 | |
|-------------------|---------|--|
| Seats | Average | |
| Carpets | Average | |
| Panels | Good | |
| Dashboard | Good | |

| C | <u></u> |
|---------|----------|
| uenerai | Comments |

Nice car.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Daryll Timms Inspected by: 11 Jun 2019 Date:

| | Pass | Fail | N/A | | | | |
|--|----------------------------|------|-----|--|--|--|--|
| Engine | | | | | | | |
| Oil level | ~ | | | | | | |
| Smoke & fumes | V V | | | | | | |
| Performance | ~ | | | | | | |
| Noise | ~ | | | | | | |
| Cooling System | • | | | | | | |
| Coolant condition | ~ | | | | | | |
| Performance | ~ | | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | | |
| Transmission | | | ı | | | | |
| Operation | ~ | | | | | | |
| Noise | ~ | | | | | | |
| Clutch | | | ~ | | | | |
| CV joints | ~ | | | | | | |
| Wheel bearings | ~ | | | | | | |
| Brakes | | | | | | | |
| Performance | V | | | | | | |
| Hand Brake | ~ | | | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | | | |
| Left front | | .0 | mm | | | | |
| Right front | | | mm | | | | |
| Left rear | 2.0 4.0 | | mm | | | | |
| Right rear | | - | mm | | | | |
| Spare | 5.0 Yes | | | | | | |
| Suspension | | 103 | | | | | |
| Suspension performance | V | | | | | | |
| Steering performance | <i>y</i> | | | | | | |
| Shock absorbers | · · | | | | | | |
| Air Conditioning / Heater | | | | | | | |
| Operation Operation | ./ | | | | | | |
| Electrical / Accessories | | | | | | | |
| Head lights | | | | | | | |
| Tail lights | ./ | | | | | | |
| Indicators | ./ | | | | | | |
| Dashboard warning lights | | | | | | | |
| Wipers (front & rear) | ./ | | | | | | |
| Window winder FL | V V V V V V | | | | | | |
| Window winder FR | | | | | | | |
| | | | | | | | |
| Window winder RL | • | | | | | | |
| Window winder RR | , | | | | | | |
| Rear view mirrors | • | | | | | | |
| Radio (basic test only) | | | | | | | |
| CD (basic test only) | ~ | | | | | | |
| Number of keys | 2 | | | | | | |
| Central locking | • | | | | | | |
| Remote locking | - | | | | | | |
| Sat. Nav. (basic test only) | _ | | ~ | | | | |
| Reversing camera | | | | | | | |
| - 444 000 | | _ | | | | | |

I have read and understood this condition guide.

Name:

Signature: