

Basic Vehicle Condition Guide

Report ID: 19,518,020


Version: 1

Created: 11 Jun 2019

Make: Model: Holden Vectra **Body Style:** Sedan Year: 2004 Registration: CFQ622 Reg Expiry: 23 Jul 2019 WoF Expiry: **Odometer: Good No:** 22 Aug 2019 240,729 Kms 19518020 VIN: W0L0ZCF6941056299 Next Service: 234,367 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front windscreen crack

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Large engine oil leak

| Interior Comments | | | |
|-------------------|---------------------------------------|--|--|
| Seats | drivers seat ripped left front stains | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

lan Dunn

Evidence of Cam Belt Replacement: No Kms:

| | Pass | Fail | N/A | |
|--|---------------------------------------|------|-----|--|
| Engine | | | | |
| Oil level | | ~ | | |
| Smoke & fumes | > | | | |
| Performance | <i>y</i> | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | > | | | |
| Transmission | | | | |
| Operation | ' | | | |
| Noise | > | | | |
| Clutch | | | ~ | |
| CV joints | V | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | > | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 1.8 | | mm | |
| Right front | 3.2 | | mm | |
| Left rear | 2.7 | | mm | |
| Right rear | 3.1 | | mm | |
| Spare | Yes | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | V | | | |
| Shock absorbers | > | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | > | | | |
| Dashboard warning lights | > | | | |
| Wipers (front & rear) | > > > > > > > > > > > > > > > > > > > | | | |
| Window winder FL | ~ | | | |
| Window winder FR | V | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | • | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |
| | | | | |

I have read and understood this condition guide.

Name:

Signature:

11 Jun 2019

Date: