

Report ID: 19,518,524 Version: 1 12 Jun 2019 Created:

Make:	Citroen	Model:	C5	Body Style:	Sedan		Pass	Fail	N/A
Year:	2012	Registration:	GMG715	Reg Expiry:	29 Jul 2019	Engine	1		I
WoF Expiry:		Odometer:	194,840 Kms	Good No:	19518524	Oil level	~		
VIN:	VF7RDRHHABL547457	Next Service:	206000	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Danta harra nat	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	s s	-0	S S		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defect						Noise	~	•	
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W SC S P SC P SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	() ()
FR park light not working FR door operation noisy						Left front 6.5 mm			
FL sun visor light not working						Right front	6.	-	mm
						Left rear	6.		mm
Condition	- Dunin - De du la s		2			Right rear			mm
Conditions During Body Inspection: Dry						Right rear 6.5 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2WD						Suspension performance	~		
Oil leak around engine and transmission area (underbody covered)						Steering performance	~		
FR and FL Ja	ack point dent					Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats FR seat worn						Head lights			
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Transmission jerking from D2 to D3						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Car	ditions During Test					Central locking	2 V		
	uning resi		Dry			Remote locking	~		
Engine Tir	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 124,872						Reversing camera			~
	•								,
Inspected by: Sudhin Ramachandran Date: 12 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: