

 Report ID:
 19,519,248

 Version:
 3

 Created:
 29 Jun 2019

Make:	Nissan	Model:	Tiida	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2007	Registration:	HQQ539	Reg Expiry:	04 Jul 2019	Engine	1 1		1	
WoF Expiry:	24 Jun 2020	Odometer:	77,881 Kms	Good No:	19519248	Oil level	~			
VIN:	7AT0DH78X14017111	Next Service:	87800	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional o	charge.	Coolant condition	~			
	S				Р	Performance	~			
Key:				5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
R = rust	sc			210		Operation	~			
PT = paint defe	ect NP				11111	Noise	~			
C = crack					РТ	Clutch			~	
P = pin dent	PT SC				2416	CV joints	~			
* = decals		10		10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W – signinean	W		P		S D	Performance	~			
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
R/F Seat Worn , W/Screen chip left side.						Tyres (lowest observed tread depth of tyres)				
						Left front	8.0 mm			
						Right front	8.	0	mm	
						Left rear	8.	0	mm	
Conditions During Body Inspection: Dry						Right rear	6.0 mm			
						Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Minor surface rust on underbody of Vehicle.						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Cometa	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
	_					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
-	ming Mechanism:	Sat. Nav. (basic test only)			~					
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Chris Buckley Date: 13 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....