

Report ID: 19,519,529 Version: 1 12 Jun 2019 Created:

Signature:

Make:	Subaru	Model:	Legacy	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2002	Registration:	MDZ982	Reg Expiry:	21 Dec 2019	Engine				
WoF Expiry:	15 Nov 2019	Odometer:	242,152 Kms	Good No:	19519529	Oil level	~			
VIN:	7A8GF0B0707016959	Next Service:	245000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	V			
					C D CC	Performance	~			
Key:	L	-0	S P SC S P SC	-01-	S P SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent B = rust SDC SDC						Operation 🖌				
R = rust PT = paint defe				\prod	JUIL	Noise	~			
C = crack				+	SC	Clutch			~	
P = pin dent					세비	CV joints	~			
* = decals SDSC 919 SDSC						Wheel bearings	· ·			
SC = stone chips							Brakes			
W = significant scuffs S SC S D SC S D SC S D SC						Performance	~			
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre))	
Minor stone chips in the windscreen ,both mirrors are scuffed,						Left front 4 mm				
						Right front			mm	
						Left rear		4		
								4	mm	
Conditions During Body Inspection: Dry						Right rear	4 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension				
	inage a onder bor	meenspeede				•				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
wear and tear minor stains worn						Electrical / Accessories				
Seats			,,			Head lights	~			
Carpets	wear and t	tear,worn,minor	stains ,			Tail lights	~			
	door trims	need attention				Indicators	~			
Panels			,			Dashboard warning lights	~			
Dashboa	rd car has 2 k	eys one starts ca	r the other opens,			Wipers (front & rear)	~			
						Window winder FL	~			
Canada						Window winder FR	~			
General	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Donovan Matara Date: 12 Jun 2019										

I have read and understood this condition guide.

Name: