



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,520,075
Version:	2
Created:	14 Jun 2019

Make:	Mazda	Body Style:	
Model:	Axela	VIN:	7AT0C13JX19111880
Year:	2010	Odometer:	106,610 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	✓	Cooling System			78	Under Carriage	Good	Exterior				
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation	•					
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good					
4	High Stop Light	✓	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good					
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good					
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good					
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	Wheels and Tyres							
8	Rear Left Indicators	✓	37	CV Joints	✓				85	R/H Mirror	Good					
9	Reversing Lights	✓	38	Wheel Bearing	✓				61	Left Front	7.0	86	L/H Mirror	Good		
10	Rear Reflectors	✓	39	Wheel Balance	✓				62	Right Front	7.0	87	L/F Guard	Good		
11	Hazard Lights	✓	40	Gearbox (Manual)	•				63	Left Rear	6.0	88	R/F Guard	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	64	Right Rear	6.0	89	L/H Doors	Good					
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	N/A	90	R/H Doors	Good					
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		66	Tools	✓	91	L/H Sill	Good					
15	Number Plate Light	✓	Brakes			Interior			92	R/H Sill	Good					
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	67	AC Operation	✓	93	Boot/Tail Gate	Good					
17	Speedo	✓	45	Rear Brakes	✓	68	Heater Fan	✓	94	Front Bumper	Good					
18	Odometer	✓	46	Handbrake	✓	69	Seatbelts	✓	95	Rear Bumper	Good					
19	Rev Counter	✓	Keys and Locking			70	Horn	✓	96	Roof	Good					
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	97	Bonnet	Good					
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	98	Fuel Cap	✓					
22	Window Opener FL	✓	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps	✓					
23	Window Opener FR	✓	Engine			74	Seats	Average	100	WOF	✓					
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good								
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Average								
26	Rear View Mirrors	✓	52	Performance	✓	77	Dashboard	Good								
27	Radio (Basic Test Only)	✓	53	Noise	✓											
28	CD (Basic Test Only)	✓	54	Starter Motor	✓											
29	Boot Open Switch	✓														

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Ca Thach	Date:	13 Jun 2019
---------------	----------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--