



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,521,219
Version:	1
Created:	14 Jun 2019

Make:	Nissan	Body Style:	
Model:	Elgrand	VIN:	7AT0DH6MX19003692
Year:	2010	Odometer:	99,638 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30 Fuel Flap Release		Cooling System		Exterior				
1	Battery	31	Reversing Camera	55	Coolant Condition	78	Under Carriage	Good		
2	Headlights	32	USB Port	56	Performance	79	Sun Roof Operation	<input type="checkbox"/>		
3	Tail Lights	33	Window Lock Switch	57	Radiator/Hoses (visual)	80	Front Windscreen (no chips)	Good		
4	High Stop Light	<b>Transmission and Drive</b>		<b>Suspension</b>		81	Back Windscreen (no chips)	Good		
5	Front Right Indicators	34	Operation	58	Suspension Performance	82	Side Windows (no chips)	Good		
6	Front Left Indicators	35	Noise	59	Steering Performance	83	Front Wiper Blades	Good		
7	Rear Right Indicators	36	Clutch	60	Shock Absorbers	84	Rear Wiper Blade	Good		
8	Rear Left Indicators	37	CV Joints	<b>Wheels and Tyres</b>		85	R/H Mirror	Good		
9	Reversing Lights	38	Wheel Bearing	61	Left Front	5.5	86	L/H Mirror	Good	
10	Rear Reflectors	39	Wheel Balance	62	Right Front	5.5	87	L/F Guard	Good	
11	Hazard Lights	40	Gearbox (Manual)	63	Left Rear	5.5	88	R/F Guard	Good	
12	Courtesy Lights	41	Engine Timing	Timing Chain	64	Right Rear	5.5	89	L/H Doors	Good
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes	90	R/H Doors	Good
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)		66	Tools	<input checked="" type="checkbox"/>	91	L/H Sill	Good
15	Number Plate Light	<b>Brakes</b>		<b>Interior</b>		92	R/H Sill	Good		
16	Dashboard Warning Lights	44	Front Brakes	67	AC Operation	93	Boot/Tail Gate	Good		
17	Speedo	45	Rear Brakes	68	Heater Fan	94	Front Bumper	Good		
18	Odometer	46	Handbrake	69	Seatbelts	95	Rear Bumper	Good		
19	Rev Counter	<b>Keys and Locking</b>		70	Horn	96	Roof	Good		
20	Fuel Gauge	47	Central Locking	71	Seat Heaters	97	Bonnet	Good		
21	Wipers Front/Rear	48	Remote Locking	72	Sun Visors	98	Fuel Cap	<input checked="" type="checkbox"/>		
22	Window Opener FL	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	<input checked="" type="checkbox"/>			
23	Window Opener FR	<b>Engine</b>		74	Seats	Good	99	Mud Flaps	<input checked="" type="checkbox"/>	
24	Window Opener RL	50	Oil Level	75	Carpets	Good	100	WOF	<input checked="" type="checkbox"/>	
25	Window Opener RR	51	Smokes and Fumes	76	Panels	Good				
26	Rear View Mirrors	52	Performance	77	Dashboard	Good				
27	Radio (Basic Test Only)	53	Noise							
28	CD (Basic Test Only)	54	Starter Motor							
29	Boot Open Switch									

**Turners Certification Key:**  
 ✓ = Pass  
 X = Fail  
 • = Not applicable for this vehicle

Inspected by:	Sudhin Ramachandran	Date:	14 Jun 2019
<b>I have read and understood this condition guide:</b>			
Name:		Signature:	