

Basic Vehicle Condition Guide

Report ID: 19,521,938


Version:

Created: 06 Aug 2019

Make: Model: Mercedes-Benz C240 **Body Style:** Sedan Year: 2003 Registration: EQQ420 Reg Expiry: 20 Dec 2019 WoF Expiry: **Odometer:** 30 Jul 2020 102,038 Kms **Good No:** 19521938 VIN: WDC2030612R126006 Next Service: 115000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

•

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

Genera	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 25 Jun 2019

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			_
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.0	mm
Right front	3.0		mm
Left rear	3.0 mn		mm
Right rear	3	3.0 mm	
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			'

Signature: