

Report ID: 19,523,904 Version: 1 18 Jun 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GSQ419	Reg Expiry:	27 Feb 2020	Engine	1		
WoF Expiry:	01 Feb 2020	Odometer:	212,237 Kms	Good No:	19523904	Oil level	~		
VIN:	MNTCPGD22A000076	Next Service:	218500	Service Histor	<b>y:</b> Yes	Smoke & fumes	r		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
			Р			Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SD DA			215	HIVD	Operation	~		
PT = paint defe	ect NP	r I		$\left[ \left( \right) \right]$	701h	Noise	~		
C = crack					D SC	Clutch	~		
P = pin dent	ING HIP				74116	CV joints	~		
* = decals	DSC 916			10		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D D P S D						Performance	~		
Body Inst	paction Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Aerial mast Broken, Rear seat Burn hole,						Tyres (lowest observed tread depth of tyres)			es)
						Left front 7.0 m			mm
						Right front	5.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil seepage	e lower engine area, Mir	nor Surface Rust o	on underbody of Vehic	le.		Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by Chris Puckley						Deta: 10 lur 20	10		
Inspected by: Chris Buckley Date: 18 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....