

## **Basic Vehicle Condition Guide**

Report ID: 19,523,970


Version: 2

Created: 17 Jun 2019

Make: Model: Suzuki Escudo **Body Style:** Wagon Year: 2001 Registration: ESD141 Reg Expiry: 22 Jun 2019 WoF Expiry: **Odometer:** 02 Aug 2019 275,130 Kms **Good No:** 19523970 VIN: 7A8GK4M0708150587 **Next Service:** 290000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Front window has a couple stone chips

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

engine oil leak

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Inspected by: Timothy Love

Cleate	<u> </u>	Juli Z						
	Pass	Fail	N/A					
Engine								
Oil level	~							
Smoke & fumes	✓ ✓							
Performance	~							
Noise	~							
Cooling System								
Coolant condition	~							
Performance	V							
Radiator / Hoses (visual)	~							
Transmission								
Operation	~							
Noise	~							
Clutch			~					
CV joints	~							
Wheel bearings	~							
Brakes		1	1					
Performance	~							
Hand Brake	~							
Tyres (lowest observed tread	l depth	of tyre	 es)					
Left front		.0	mm					
Right front	5.2		mm					
Left rear		.6	mm					
Right rear		.5 .5	mm					
Spare	,	Yes						
Suspension		103						
Suspension performance	~							
Steering performance	<i>y</i>							
Shock absorbers	<i>'</i>							
Air Conditioning / Heater	_							
Operation	<b>V</b>							
Electrical / Accessories								
Head lights	./							
Tail lights	•							
Indicators	•							
Dashboard warning lights	•							
Wipers (front & rear)	•							
Window winder FL								
Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \							
Window winder RL								
Window winder RR	<b>V</b>							
Rear view mirrors	•							
	<b>V</b>							
Radio (basic test only)								
CD (basic test only)	~							
Number of keys	2							
Central locking	· ·		ļ .					
Remote locking			<b>'</b>					
Sat. Nav. (basic test only)			<b>'</b>					
Reversing camera								

I have read and understood this condition guide.

Name <sup>,</sup>			

Signature: .....

17 Jun 2019

Date: