

Report ID: 19,524,039 Version: 1 Created: 17 Jun 2019

Make:	Mitsubishi	Model:	Galant	Body Style:	Sedan		Pass	Fail	N/A
Year:	1999	Registration:	BEF342	Reg Expiry:	06 Jul 2019	Engine		·	
WoF Expiry:	18 Jul 2019	Odometer:	114,894 Miles	Good No:	19524039	Oil level	~		
VIN:	JMASNEA2AWZ00069	Next Service:	121000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	
						Performance	~	-	
Key:	SC	-0	SC	-161-	DC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		
D = dent	D SC DIC			TIN	SD SD	Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch	~		
P = pin dent						CV joints	~		
* = decals	sc pip			AL.	ELTR PT	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs						Performance			1
Note: come defects & blomiches may not be displayed in the diagram							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<i>с.</i>	Ļ
Rust on Firewall ,						Tyres (lowest observed tread depth of tyres)			
						Left front		.0	mm
						Right front		.0	mm
L						Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments L/F Tyre worn inside shoulder & R/F, oil seepage lower engine area, Rust on underbody of Vehicle.						Suspension			
L/F Tyre wo	rn inside shoulder & R/F	, oil seepage lo	wer engine area, Rust o	on underbody of	Vehicle.	Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments Gear Change a bitt stiff getting into Second gear , once warmed up was ok .						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		I
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	•	-							-
Inspected by: Chris Buckley Date: 17 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: