

Report ID: 19,524,136 Version: 4 24 Jul 2019 Created:

Make:	BMW	Model:	X5	Body Style:	SUV		Pass	Fail	N/A
Year:	2007	Registration:	LEN847	<b>Reg Expiry:</b>	04 Aug 2019	Engine			<u></u>
WoF Expiry:	19 Feb 2020	Odometer:	106,779 Kms	Good No:	19524136	Oil level	~		
VIN:	WBAFE42080LK90869	Next Service:	115469	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S S		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC						Operation 🖌			
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals S 919 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S S S S S S S S S S S S S S						Performance	~		
Body Incr	naction Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	depth	of tyre	es)
Tail door bmw badge missing Stone chips on the windscreen									mm
						Right front	4.		mm
						Left rear	4	-	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	 		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
AWD						Suspension performance	~		
Steering performance						~			
Shock absorbers							~		
Air Conditioning / He									
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	sunroof lin	ing falls				Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
			•			Remote locking	~		
-	ning Mechanism:	Timing (				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Sudhin Ramachandran Date: 24 Jul 2019									
Inspected by: Sudhin Ramachandran Date: 24 Jul 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....