

Report ID: 19,524,640 Version: 1 19 Jun 2019 Created:

Make:	Mitsubishi	Model:	Canter	Body Style:	Flatdeck		Pass	Fail	N/A
Year:	2004	<b>Registration:</b>	HBH595	Reg Expiry:	08 Oct 2019	Engine	1		1
WoF Expiry:	09 May 2020	Odometer:	293,933 Kms	Good No:	19524640	Oil level	~		
VIN:	7AT0CJ0WX13510203	Next Service:	301000	Service Histor	V: No	Smoke & fumes	~		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1
						Performance	~		
Key:		-0			SD	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second se	Transmission	-		<u> </u>
D = dent	IS GIE					Operation	~		1
R = rust PT = paint def				$\int$	THA	Noise	~		
C = crack				+	S S	Clutch	~		
P = pin dent						CV joints	•		~
* = decals	ssc 916			The	ELLA SD	Wheel bearings	~		<b> </b>
SC = stone chips						Brakes	•		
W = significant scuffs						Performance	~		1
		Note: son	ne defects & blemishe	s may not be disn	laved in the diagram	Hand Brake	~		
	pection Comments	Note: son	le delects & blemisne	s may not be disp	ayed in the diagram		•	oftur	) )
Scratches pin dents back of cab FF lens cracked						Tyres (lowest observed tread depth of tyres)   Left front 5			
						Right front			mm
						Left rear	_	.3	mm
							6	-	mm
Conditions During Body Inspection: Dry						Right rear	6.2 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		meenspeen	<u>on comments</u>			Suspension			1
Very dirty						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Poor						Electrical / Accessories			
Seats						Head lights	~		<u> </u>
Carpets	Poor					Tail lights	~		<u> </u>
	Door					Indicators	~		
Panels	Poor					Dashboard warning lights	~		<u> </u>
Dashboa	rd Poor					Wipers (front & rear)	~		<b> </b>
						Window winder FL	~		<u> </u>
Canada						Window winder FR	~		<u> </u>
General Comments Warning light on dash						Window winder RL			~
warning lig	ni on uasn					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)			~
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
								-	
Inspecte	d by: Stuart Melbourr	ne				Date: 19 Jun 20	19		
		_							

I have read and understood this condition guide.

Name: .....

Signature: .....