

Report ID: 19,525,249 Version: 1 18 Jun 2019 Created:

Make:	Volvo	Model:	S40	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	Registration:	GKZ478	Reg Expiry:	08 Jul 2019	Engine			
WoF Expiry:	17 Jul 2019	Odometer:	166,361 Kms	Good No:	19525249	Oil level	~		
VIN:	YV1MS664952109463	Next Service:	162000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	lis can be analiged ic		inarge.	Coolant condition	~		
	S W		SD SD		S	Performance	~		
Key: 30 30 30 W						Radiator / Hoses (visual)	~		
						Transmission			
B = rust PT C SC W						Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc				24116	CV joints	~		
r = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs SD W SD SD W S						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Right wing mirror cover missing and held together with tape						Tyres (lowest observed tread depth of tyres)			es)
					Left front 6			mm	
						Right front	5 mm		mm
					Left rear	6 m		mm	
Conditions During Body Inspection: Dry					Right rear	6 mm		mm	
					Spare Yes				
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Mirrors don't fold in					Suspension performance		~		
Roof lining sagging Power steering leak						Steering performance		~	
Information warning light stays on						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	worn					Head lights	~		
Correcto	driver mat	hole				Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights		>	
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Knock in front and rear suspension Shudder on steering wheel when accelerating						Window winder RR	~		
Engine noise at idle					Rear view mirrors		>		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 18 Jun 2019									
Inspected by: John Lindsay Date: 18 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: