

C = ctopo chipc		wheel bearings	V	
SC = stone chips W = significant scuffs		Brakes		
		Performance	~	
Body Inspection	Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
<u>,</u>		Tyres (lowest observed tread depth of tyres)		
		Left front	6.0	mm
		Right front	6.0	mm
		Left rear	3.0	mm
Conditions During Body Inspection: Dry		Right rear	2.0	mm
		Spare	Y	es
Under Carriage & Under Bonnet Inspection Comments		Suspension		
		Suspension performance	~	
		Steering performance	~	
		Shock absorbers	~	
		Air Conditioning / Heater		
		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Good	Head lights	~	
	Good	Tail lights	~	
Carpets		Indicators	~	
Panels	Good	Dashboard warning lights	~	
	Good	Wipers (front & rear)	~	
Dashboard		Window winder FL	~	
		Window winder FR	~	
General Comments		Window winder RL	~	
		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
		CD (basic test only)	~	
		Number of keys	2	
Road Conditions During Test Drive: Dry		Central locking	~	
	- <i>·</i>	Remote locking	~	
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)		~
Evidence of Cam	Belt Replacement: Not Applicable Kms:	Reversing camera	~	
	Brian Hill	Date: 18 Jun 201		

I have read and understood this condition guide.

Name:

Signature:

N/A

V