

Basic Vehicle Condition Guide

Report ID: 19,525,895


Version: 2

Created: 23 Jul 2019

Make: Model: Mazda Mazda6 **Body Style:** Sedan Year: 2007 Registration: MEY403 Reg Expiry: 05 Jul 2019 WoF Expiry: **Odometer: Good No:** 23 Jul 2020 243,024 Kms 19525895 VIN: JM0GG103200531230 Next Service: 241,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Commo	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\triangle \)			
Noise	~			
Cooling System			1	
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission		!	•	
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		5	mm	
Right front	6		mm	
Left rear	4		mm	
Right rear	4		mm	
Spare		Yes		
Suspension	•			
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	<i>'</i>			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			~	

I have read and understood this condition guide.

Name:

Signature:

23 Jul 2019

Date: