

Basic Vehicle Condition Guide

Report ID: 19,526,141

Pass

~

~

1

1

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Coolant condition Performance

Radiator / Hoses (visual)

18 Jun 2019 Created:

Fail


N/A

1

Make: Model: Toyota Hiace **Body Style:** Van Year: 2011 Registration: GBW749 Reg Expiry: 17 Aug 2019 WoF Expiry: **Odometer: Good No:** 164,218 Kms 19526141 VIN: Next Service: 172,000 JTFPT22P900008178 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip on front windscreen Spare tyre damaged Front bumper RH trim missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

2WD

Turbo hose leak

<u>Interior Comments</u>				
Seats	Driver's seat wear and tear			
Carpets	Average			
Panels	Average			
Dashboard	Good			

General Comments

Whining noose from differential

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms:

	Hand Brake	~						
	Tyres (lowest observed tread depth of tyres)							
	Left front	6	5	mm				
	Right front	6	5	mm				
_	Left rear	3	3	mm				
	Right rear	3	3	mm				
_	Spare		Yes					
	Suspension	Suspension						
	Suspension performance	~						
	Steering performance	~						
	Shock absorbers	~						
	Air Conditioning / Heater							
_ 	Operation	~						
	Electrical / Accessories	Electrical / Accessories						
	Head lights	~						
	Tail lights	~						
	Indicators	~						
	Dashboard warning lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						
	Wipers (front & rear)	~						
	Window winder FL	~						
_	Window winder FR	~						
	Window winder RL			~				
	Window winder RR			~				
	Rear view mirrors	~						
	Radio (basic test only)	~						
	CD (basic test only)	~						
	Number of keys	2						
٦	Central locking	~						
_ ¬	Remote locking		~					
	Sat. Nav. (basic test only)			~				
I	Reversing camera			~				

Inspected by:	Mathew Varghe	c۵

have road	and und	erstand this	c condition	auida

Name:			

18 Jun 2019

Date: