

Report ID: 19,526,322 Version: 2 08 Oct 2019 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:		Engine			1
WoF Expiry:	10 Jun 2020	Odometer:	102,014 Kms	Good No:	19526322	Oil level	~		
VIN:	7AT0C139X19101978	Next Service:	106,937kms	Service Histor	'y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	- HE			715		Operation	~		
PT = paint defe	ect NP	FI		$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIC				74114	CV joints	~		-
* = decals	- Alf			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant	t scuffs					Performance	~		
Dadular		Note: son	ne defects & blemishes	may not be disr	blayed in the diagram	Hand Brake	~		
Body Insp	pection Comments			,	, ,	Tyres (lowest observed tread	depth	of tyre	l s)
									mm
						Right front	5.		mm
						Left rear	3		mm
Conditions Duving Pody Inspection						Right rear			mm
Conditions During Body Inspection: Dry						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	v v		
General C	Comments					Window winder RL	v v		
						Window winder RL	v v		
						Rear view mirrors	v v		
						Radio (basic test only)	<i>v</i> <i>v</i>		
						CD (basic test only)	v v		
						Number of keys			
						Central locking	2		
Road Conditions During Test Drive: Dry						-	v		
Engine Tir	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: Bobby Zhong Date: 08 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: