

## **Basic Vehicle Condition Guide**

Report ID: 19,526,461


Version: 1

Created: 10 Jul 2019

Make: Model: Ford Mondeo **Body Style:** Hatchback Year: 2012 Registration: GNP277 Reg Expiry: 02 Oct 2013 WoF Expiry: **Odometer:** 24 Oct 2019 76,639 Kms **Good No:** 19526461 VIN: WF0EXXGBBECK20632 Next Service: 90872 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

**General Comments** 

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Inspected by: Melissa Haggerty

Pass	Fail	N/A		
Engine				
~				
~				
/				
~				
Cooling System				
~				
>				
/				
Transmission				
~				
~				
		~		
~				
~				
Brakes				
~				
<b>'</b>				
l depth	of tyre	es)		
7	.6	mm		
8.1		mm		
6.9		mm		
7.3		mm		
	Yes			
~				
<b>'</b>				
~				
Air Conditioning / Heater				
~				
Electrical / Accessories				
<b>'</b>				
<b>'</b>				
~				
<b>'</b>				
>				
<b>'</b>				
~				
~				
~				
~				
~				
~				
2				
<b>/</b>				
~				
		<b>'</b>		
		~		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V		

I have read and understood this condition guide.

Name: .....

Signature: .....

10 Jul 2019

Date: