

Report ID: 19,527,315 Version: 1 23 Jun 2019 Created:

Signature:

Make:	Ford	Model:	Mondeo	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	DNS762	Reg Expiry:	01 Apr 2019	Engine	1		
WoF Expiry:	25 Jan 2020	Odometer:	131,841 Kms	Good No:	19527315	Oil level	~		
VIN:	WF04XXGBB46U2833	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	or an additional o	inarge.	Coolant condition	~		
	S C		S S		S D	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S D PT			10	Ell s	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					S R	Clutch			~
P = pin dent	s sc dR				7411 <u>6</u>	CV joints	~		
^= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs SD DW SD						Performance	~		
 Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Rear bumper misaligned, LH reflector insecure						Tyres (lowest observed tread	d depth	of tyre	es)
LH wing mirror & fender indicator broken. FL wheel cap missing						Left front	4	1	mm
Front grille broken, insecure, logo missing. Bonnet misaligned, not closing properly. Front windscreen moulding peeling. Driver's door getting stuck						Right front	1		mm
Front bumper bottom part broken, missing						Left rear	2	2	mm
Conditions During Body Inspection: Dry						Right rear	3	3 mn	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2WD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good				Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Engine noise coming to the interior Noise from gear shift lever in P position					Window winder RR	~			
Noise Ironi		luon				Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1		
Inspected by: Mathew Varghese Date: 23 Jun 2019									

I have read and understood this condition guide.

Name: