

Report ID: 19,528,234 Version: 3 03 Jul 2019 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:	FEA62	Reg Expiry:	20 Jul 2019	Engine			
WoF Expiry:	26 Jun 2020	Odometer:	239,540 Kms	Good No:	19528234	Oil level	~		
VIN:	KMHDC51TMAU22099	Next Service:	240,000	Service Histor	y: No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S SC		S D P S	W	SC	Performance	~		
Key:	1330	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			715	HIVS	Operation	~		
PT = paint defect						Noise	~		
C = crack					SC	Clutch			~
P = pin dent	s sc dP			$\langle \rangle$	74116	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P S SC S SC						Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	r		
Body Inspection Comments Damage on RF door. Poor paint repair on front of LHF guard.						Tyres (lowest observed tread depth of tyres)			es)
Sumage of the door, tool paint repair of front of Ern guard.					Left front 5			mm	
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear		4	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Ok						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	V		
						Air Conditioning / Heater	I		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	/ verage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
Drives ok.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1	1	
Inspected by: Roger King Date: 03 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: