

## **Basic Vehicle Condition Guide**

Report ID: 19,528,674


Version: 1

Created: 20 Jun 2019

Make: BMW Model: 335i **Body Style:** Coupe Year: 2008 Registration: HLL400 Reg Expiry: 22 Feb 2020 WoF Expiry: **Odometer: Good No:** 26 Jun 2020 168,713 Kms 19528674 VIN: WBAWB72050P05471 Next Service: 176000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Minor stone chips in the windscreen,

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Unknown

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Donovan Matara Inspected by:

Name: .....

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	> >		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			1
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	5		mm
Right front	5		mm
Left rear	6		mm
Right rear	6		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		ļ	ļ
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			1
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	<u>'</u>		
Remote locking	<i>y</i>		
Sat. Nav. (basic test only)			1
Reversing camera			./
versning curnera			

20 Jun 2019

Signature: .....

Date: