

Basic Vehicle Condition Guide

Report ID: 19,530,127


Version: 6

Created: 26 Jul 2019

Make: Model: Nissan Altima **Body Style:** Sedan Year: 2014 Registration: HJD951 Reg Expiry: 16 Jan 2020 WoF Expiry: **Odometer: Good No:** 01 Aug 2020 89,714 Kms 19530127 VIN: MNTBCAL33A0001369 Next Service: 71,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comme	<u>nts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 26 Jul 2019

Name:

	Pass	Fail	N/A
Engine	1		
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		†
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front			mm
Right front	3		mm
Left rear	5		mm
Right rear	5		mm
Spare	Yes		
Suspension		103	
Suspension performance	~		
Steering performance	<i>y</i>		+
Shock absorbers	~		+
Air Conditioning / Heater			
Operation	~		Т
Electrical / Accessories	V		
Head lights			
Tail lights	<i>V</i>		
Indicators	V		
Dashboard warning lights			
	\(\triangle \)		
Wipers (front & rear)			
Window winder FL	'		
Window winder FR	<i>v</i>		
Window winder RL	'		
Window winder RR	•		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	ı	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	′		

Signature: