

Report ID: 19,530,324 Version: 2 24 Jun 2019 Created:

Signature: .....

Make:	BMW	Model:	3181	Body Style:	Sedan		Pass	Fail	N/A
Year:	2002	<b>Registration:</b>	GRD638	Reg Expiry:	03 Jan 2020	Engine	1		I
WoF Expiry:	27 Mar 2020	Odometer:	108,744 Kms	Good No:	19530324	Oil level	~		
VIN:	WBAAZ72060NG0960	Next Service:	118000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and milages	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	s w	-0	S SD	-	SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SC W S W						Operation	~		
R = rust PT = paint defe				$\prod$	JHIH	Noise	~		
C = crack					PT SC	Clutch	•		~
P = pin dent						CV joints	~		
* = decals	S PT SC 916			The	ET SPT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SPT W SD SD W SD						Performance	~		
		Note: som	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftyre	) )
Left fog light condensation Left front under tray loose/damaged									mm
	naci ilay loose, aamage					Right front			-
						Left rear			mm mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Radio not working						Suspension			
Remotes not working						Suspension performance	~		
Engine oil le	eak					Steering performance		~	
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
driver seat worp						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	doorpana	ls scratchad from	t left door fabric loose			Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd coating pe	aling				Wipers (front & rear)	~		
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		
General Comments Steering wheel not centre						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
	ning Masharitan	<b>T</b> !	<sup>c</sup> hain			Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 24 Jun 2019									

I have read and understood this condition guide.

Name: .....