

Basic Vehicle Condition Guide

Report ID: 19,530,416

Version: 3

Engine

Oil level

Created: 10 Jul 2019

Pass


Fail

N/A

Make: Model: **Body Style:** Holden Colorado Utility Year: 2016 Registration: JTZ976 Reg Expiry: 18 Aug 2019 WoF Expiry: **Odometer: Good No:** 13 May 2020 71,952 Kms 19530416 VIN: MMU148EK0GH63884 Next Service: 80480 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RR and RL window vibration while open

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

2WD

Minor oil weep

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

One remote manual key spring faulty

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Smoke & fumes	~				
Performance	~				
Noise	~				
Cooling System		•			
Coolant condition	~				
Performance	ン				
Radiator / Hoses (visual)	>				
Transmission		•			
Operation	~				
Noise	~				
Clutch			~		
CV joints			~		
Wheel bearings	~				
Brakes		•			
Performance	>				
Hand Brake	'				
Tyres (lowest observed tread depth of tyres)					
Left front	:	8	mm		
Right front	nt front		mm		
Left rear	4.5		mm		
Right rear	3.5		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	•				
Wipers (front & rear)	~				
Window winder FL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	•				
CD (basic test only)			'		
Number of keys	2				
Central locking	'				
Remote locking	~				
Sat. Nav. (basic test only)			1		

I have read and understood this condition guide.

Sudhin Ramachandran

Name:

Signature:

10 Jul 2019

Reversing camera