



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

|            |             |
|------------|-------------|
| Report ID: | 19,530,714  |
| Version:   | 1           |
| Created:   | 24 Jun 2019 |

|                                    |         |             |                   |
|------------------------------------|---------|-------------|-------------------|
| Make:                              | Toyota  | Body Style: | Wagon             |
| Model:                             | Caldina | VIN:        | 7AT0H624X19014068 |
| Year:                              | 2004    | Odometer:   | 48,423 Kms        |
| Road Conditions During Test Drive: | Dry     |             |                   |

| Electrical |                          |   | 30                     | Fuel Flap Release                | ✓              | Cooling System   |                           |      | 78  | Under Carriage              | Good | Exterior |  |  |
|------------|--------------------------|---|------------------------|----------------------------------|----------------|------------------|---------------------------|------|-----|-----------------------------|------|----------|--|--|
| 1          | Battery                  | ✓ | 31                     | Reversing Camera                 | ✓              | 55               | Coolant Condition         | ✓    | 79  | Sun Roof Operation          | •    |          |  |  |
| 2          | Headlights               | ✓ | 32                     | USB Port                         | •              | 56               | Performance               | ✓    | 80  | Front Windscreen (no chips) | Good |          |  |  |
| 3          | Tail Lights              | ✓ | 33                     | Window Lock Switch               | ✓              | 57               | Radiator/Hoses (visual)   | ✓    | 81  | Back Windscreen (no chips)  | Good |          |  |  |
| 4          | High Stop Light          | ✓ | Transmission and Drive |                                  |                | Suspension       |                           |      | 82  | Side Windows (no chips)     | Good |          |  |  |
| 5          | Front Right Indicators   | ✓ | 34                     | Operation                        | ✓              | 58               | Suspension Performance    | ✓    | 83  | Front Wiper Blades          | Good |          |  |  |
| 6          | Front Left Indicators    | ✓ | 35                     | Noise                            | ✓              | 59               | Steering Performance      | ✓    | 84  | Rear Wiper Blade            | Good |          |  |  |
| 7          | Rear Right Indicators    | ✓ | 36                     | Clutch                           | •              | 60               | Shock Absorbers           | ✓    | 85  | R/H Mirror                  | Good |          |  |  |
| 8          | Rear Left Indicators     | ✓ | 37                     | CV Joints                        | ✓              | Wheels and Tyres |                           |      | 86  | L/H Mirror                  | Good |          |  |  |
| 9          | Reversing Lights         | ✓ | 38                     | Wheel Bearing                    | ✓              | 61               | Left Front                | 5    | 87  | L/F Guard                   | Good |          |  |  |
| 10         | Rear Reflectors          | ✓ | 39                     | Wheel Balance                    | ✓              | 62               | Right Front               | 5    | 88  | R/F Guard                   | Good |          |  |  |
| 11         | Hazard Lights            | ✓ | 40                     | Gearbox (Manual)                 | •              | 63               | Left Rear                 | 5    | 89  | L/H Doors                   | Good |          |  |  |
| 12         | Courtesy Lights          | ✓ | 41                     | Engine Timing                    | Timing Chain   | 64               | Right Rear                | 5    | 90  | R/H Doors                   | Good |          |  |  |
| 13         | Dashboard Lights         | ✓ | 42                     | Evidence of Cam Belt Replacement | Not Applicable | 65               | Spare                     | Yes  | 91  | L/H Sill                    | Good |          |  |  |
| 14         | Dashboard Dimmer Switch  | • | 43                     | Replaced at (odometer reading)   |                | 66               | Tools                     | ✓    | 92  | R/H Sill                    | Good |          |  |  |
| 15         | Number Plate Light       | ✓ | Brakes                 |                                  |                | Interior         |                           |      | 93  | Boot/Tail Gate              | Good |          |  |  |
| 16         | Dashboard Warning Lights | ✓ | 44                     | Front Brakes                     | ✓              | 67               | AC Operation              | ✓    | 94  | Front Bumper                | Good |          |  |  |
| 17         | Speedo                   | ✓ | 45                     | Rear Brakes                      | ✓              | 68               | Heater Fan                | ✓    | 95  | Rear Bumper                 | Good |          |  |  |
| 18         | Odometer                 | ✓ | 46                     | Handbrake                        | ✓              | 69               | Seatbelts                 | ✓    | 96  | Roof                        | Good |          |  |  |
| 19         | Rev Counter              | ✓ | Keys and Locking       |                                  |                | 70               | Horn                      | ✓    | 97  | Bonnet                      | Good |          |  |  |
| 20         | Fuel Gauge               | ✓ | 47                     | Central Locking                  | ✓              | 71               | Seat Heaters              | •    | 98  | Fuel Cap                    | ✓    |          |  |  |
| 21         | Wipers Front/Rear        | ✓ | 48                     | Remote Locking                   | ✓              | 72               | Sun Visors                | ✓    | 99  | Mud Flaps                   | ✓    |          |  |  |
| 22         | Window Opener FL         | ✓ | 49                     | Number of Keys                   | 1              | 73               | Sun Visors Lights/Mirrors | ✓    | 100 | WOF                         | ✓    |          |  |  |
| 23         | Window Opener FR         | ✓ | Engine                 |                                  |                | 74               | Seats                     | Good |     |                             |      |          |  |  |
| 24         | Window Opener RL         | ✓ | 50                     | Oil Level                        | ✓              | 75               | Carpets                   | Good |     |                             |      |          |  |  |
| 25         | Window Opener RR         | ✓ | 51                     | Smokes and Fumes                 | ✓              | 76               | Panels                    | Good |     |                             |      |          |  |  |
| 26         | Rear View Mirrors        | ✓ | 52                     | Performance                      | ✓              | 77               | Dashboard                 | Good |     |                             |      |          |  |  |
| 27         | Radio (Basic Test Only)  | ✓ | 53                     | Noise                            | ✓              |                  |                           |      |     |                             |      |          |  |  |
| 28         | CD (Basic Test Only)     | ✓ | 54                     | Starter Motor                    | ✓              |                  |                           |      |     |                             |      |          |  |  |
| 29         | Boot Open Switch         | ✓ |                        |                                  |                |                  |                           |      |     |                             |      |          |  |  |

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

|               |              |       |             |
|---------------|--------------|-------|-------------|
| Inspected by: | John Lindsay | Date: | 24 Jun 2019 |
|---------------|--------------|-------|-------------|

**I have read and understood this condition guide:**

|       |  |            |  |
|-------|--|------------|--|
| Name: |  | Signature: |  |
|-------|--|------------|--|