

## **Basic Vehicle Condition Guide**

Report ID: 19,530,808


Version: 2

Created: 03 Jul 2019

Make: Model: Nissan Navara **Body Style:** Utility Year: 2010 Registration: FDR313 Reg Expiry: 23 Feb 2020 WoF Expiry: **Odometer:** 25 Jun 2020 173,383 Kms **Good No:** 19530808 VIN: MNTVCUD40A000260 Next Service: 183,383 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Deck cover ripped

Front windscreen stone chips

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

| <u>Interior Comments</u> |      |  |  |  |
|--------------------------|------|--|--|--|
| Seats                    | Good |  |  |  |
| Carpets                  | Good |  |  |  |
| Panels                   | Good |  |  |  |
| Dashboard                | Good |  |  |  |

|         | _        |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

lan Dunn

**Evidence of Cam Belt Replacement:** No Kms:

|                              | Pass                  | Fail    | N/A   |
|------------------------------|-----------------------|---------|-------|
| Engine                       |                       | •       |       |
| Oil level                    | ~                     |         |       |
| Smoke & fumes                | ~                     |         |       |
| Performance                  | \( \triangle \)       |         |       |
| Noise                        | ~                     |         |       |
| Cooling System               |                       |         |       |
| Coolant condition            | ~                     |         |       |
| Performance                  | ~                     |         |       |
| Radiator / Hoses (visual)    | ~                     |         |       |
| Transmission                 |                       |         | -     |
| Operation                    | <b>V</b>              |         |       |
| Noise                        | ~                     |         |       |
| Clutch                       |                       |         | _     |
| CV joints                    |                       |         |       |
| Wheel bearings               | · ·                   |         |       |
| Brakes                       |                       |         |       |
| Performance                  | <b>V</b>              |         | I     |
| Hand Brake                   | •                     |         |       |
| Tyres (lowest observed tread | denth                 | of tyre | )<br> |
| Left front                   |                       |         | mm    |
| Right front                  |                       |         | mm    |
| Left rear                    |                       |         | mm    |
|                              |                       | .8      | -     |
| Right rear                   | 5                     | .2      | mm    |
| Spare                        |                       | Yes     |       |
| Suspension                   |                       |         |       |
| Suspension performance       | \( \triangle \)       |         |       |
| Steering performance         | •                     |         |       |
| Shock absorbers              | •                     |         |       |
| Air Conditioning / Heater    |                       |         | 1     |
| Operation .                  | •                     |         |       |
| Electrical / Accessories     |                       |         |       |
| Head lights                  | <i>\</i>              |         |       |
| Tail lights                  | <i>'</i>              |         |       |
| Indicators                   | -                     |         |       |
| Dashboard warning lights     | ~                     |         |       |
| Wipers (front & rear)        | ~                     |         |       |
| Window winder FL             | V<br>V<br>V<br>V<br>V |         |       |
| Window winder FR             | ~                     |         |       |
| Window winder RL             | ~                     |         |       |
| Window winder RR             | \( \times \)          |         |       |
| Rear view mirrors            | ~                     |         |       |
| Radio (basic test only)      | ~                     |         |       |
| CD (basic test only)         | ~                     |         |       |
| Number of keys               | 2                     | ı       |       |
| Central locking              | ~                     |         |       |
| Remote locking               | ~                     |         |       |
| Sat. Nav. (basic test only)  |                       |         | ~     |
| Reversing camera             |                       |         | V     |

I have read and understood this condition guide.

Name: .....

Signature: .....

02 Jul 2019

Date: