



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,530,906
Version:	1
Created:	24 Jun 2019

Make:	Toyota	Body Style:	Sedan
Model:	Crown	VIN:	7AT0H60BX19012782
Year:	2004	Odometer:	91,083 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	✓
1	Battery	✓	31	Reversing Camera	✓
2	Headlights	✓	32	USB Port	•
3	Tail Lights	✓	33	Window Lock Switch	✓
4	High Stop Light	✓	Transmission and Drive		
5	Front Right Indicators	✓	34	Operation	✓
6	Front Left Indicators	✓	35	Noise	✓
7	Rear Right Indicators	✓	36	Clutch	•
8	Rear Left Indicators	✓	37	CV Joints	✓
9	Reversing Lights	✓	38	Wheel Bearing	✓
10	Rear Reflectors	✓	39	Wheel Balance	✓
11	Hazard Lights	✓	40	Gearbox (Manual)	•
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)	
15	Number Plate Light	✓	Brakes		
16	Dashboard Warning Lights	✓	44	Front Brakes	✓
17	Speedo	✓	45	Rear Brakes	✓
18	Odometer	✓	46	Handbrake	✓
19	Rev Counter	✓	Keys and Locking		
20	Fuel Gauge	✓	47	Central Locking	✓
21	Wipers Front/Rear	✓	48	Remote Locking	✓
22	Window Opener FL	✓	49	Number of Keys	3
23	Window Opener FR	✓	Engine		
24	Window Opener RL	✓	50	Oil Level	✓
25	Window Opener RR	✓	51	Smokes and Fumes	✓
26	Rear View Mirrors	✓	52	Performance	✓
27	Radio (Basic Test Only)	✓	53	Noise	✓
28	CD (Basic Test Only)	✓	54	Starter Motor	✓
29	Boot Open Switch	✓			
Cooling System			55	Coolant Condition	✓
			56	Performance	✓
			57	Radiator/Hoses (visual)	✓
Suspension			58	Suspension Performance	✓
			59	Steering Performance	✓
			60	Shock Absorbers	✓
Wheels and Tyres			61	Left Front	7
			62	Right Front	7
			63	Left Rear	7
			64	Right Rear	7
			65	Spare	Yes
			66	Tools	✓
Interior			67	AC Operation	✓
			68	Heater Fan	✓
			69	Seatbelts	✓
			70	Horn	✓
			71	Seat Heaters	•
			72	Sun Visors	✓
			73	Sun Visors Lights/Mirrors	✓
			74	Seats	Average
			75	Carpets	Average
			76	Panels	Average
			77	Dashboard	Average
Exterior			78	Under Carriage	Good
			79	Sun Roof Operation	•
			80	Front Windscreen (no chips)	Good
			81	Back Windscreen (no chips)	Good
			82	Side Windows (no chips)	Good
			83	Front Wiper Blades	Good
			84	Rear Wiper Blade	Good
			85	R/H Mirror	Good
			86	L/H Mirror	Good
			87	L/F Guard	Good
			88	R/F Guard	Good
			89	L/H Doors	Good
			90	R/H Doors	Good
			91	L/H Sill	Good
			92	R/H Sill	Good
			93	Boot/Tail Gate	Good
			94	Front Bumper	Good
			95	Rear Bumper	Good
			96	Roof	Good
			97	Bonnet	Good
			98	Fuel Cap	✓
			99	Mud Flaps	✓
			100	WOF	✓

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	24 Jun 2019
I have read and understood this condition guide:			
Name:		Signature:	