

Report ID: 19,531,472 Version: 2 27 Jun 2019 Created:

Make:	Mitsubishi	Model:	Lancer	Body Style:	Sedan		Pass	Fail	N/A
Year:	1998	Registration:		Reg Expiry:	05 Jul 2019	Engine			1
		Odometer:	126,646 Kms	Good No:	19531472	Oil level	~		1
VIN:	7A8CJ0D0706206654			Service Histor		Smoke & fumes	~		
					· · · ·	Performance	~		+
	port is not a warranty	austion is d	for one such that	no Dorte la	haan diamanti l	Noise	~		+
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has been	driven up to 50kr	n/h from cold. The '	lendor recommends	Cooling System	-		1
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:		-0		<u> –</u> –		Radiator / Hoses (visual)	~		-
S = scratch	Re	A U			The second	Transmission	•		<u> </u>
D = dent	scw 6/6					Operation	~		Τ
R = rust PT = paint defe					JHIH	Noise	~		-
C = crack				$+ \mathbb{N}$		Clutch	~		
P = pin dent	Ho					CV joints	~		+
* = decals	sc 916				ELIPS-	Wheel bearings	~		+
SC = stone chi	ps U	20		LAU	&	Brakes	•		L
W = significan	t scuffs	- 0		- WF		Performance	~		τ
		Note: som	e defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		<u> </u>
<u>Body Insp</u>	pection Comments	10012. 5011		nes may not be disp	ayea in the diagram		•	oft	
						Tyres (lowest observed treat	· ·		
							5.		mm
						Right front	5.		mm
						Left rear	2.		mm
Conditions During Body Inspection: Dry						Right rear	210		mm
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	inage & onder bor		in comments			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		–
						Shock absorbers	~		
						Air Conditioning / Heater	1.1		
Interior Comments					Operation	~			
	Average					Electrical / Accessories			T
Seats						Head lights	~		─
Carpets	Average					Tail lights	~		─
	Average					Indicators	~		─
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	Average					Wipers (front & rear)	~		_
						Window winder FL	~		_
Concurl						Window winder FR	~		_
<u>General Comments</u> Front L passenger carpet is damp					Window winder RL	~		<u> </u>	
FION L pas	senger carpet is damp					Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
		Road Conditions During Test Drive: Dry					~		
Road Con	ditions During Test	t Drive:	DIY						
			•			Remote locking			~
Engine Tir	ming Mechanism:	Cambelt	:			Remote locking Sat. Nav. (basic test only)			~ ~
Engine Tir		Cambelt	•	Kms:		_			
Engine Tii Evidence	ming Mechanism:	Cambelt	:	Kms:		Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Name:

Signature: