

Report ID: 19,532,235 Version: 1 24 Jun 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2009	Registration:	EUK950	Reg Expiry:	15 Oct 2019	Engine			<u> </u>
WoF Expiry:		Odometer:	117,313 Kms	Good No:	19532235	Oil level	~		
VIN:	MMMTFR85H8H5748(Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I	.		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	sc	-0	S P P SC		S	Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent	sc			1n-		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+	SC	Clutch	~		
P = pin dent	Htc	KI			JUII —	CV joints	V		~
* = decals	SDP 90			AL-	ELP SP	Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs S P S P S P S P									1
		Note: con	ne defects & blemishes			Performance	~		
Body Ins	pection Comments	Note: son	ie delects & blemisnes	s may not be disp	hayed in the diagram	Hand Brake		<i>C</i> .	
Stonechips on windscreen. Wear on RF seat and seatbelt.						Tyres (lowest observed tread depth of tyres)			
wear on RF	seat and seatbelt.					Left front	4		mm
						Right front	4		mm
						Left rear	3		mm
Conditions During Body Inspection: Wet						Right rear	3 mm		mm
Under Corriges & Under Pennet Increation Comments						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good cond	ition.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	-					Window winder FR	~		
General Comments					Window winder RL	~			
Drives well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		·
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L						-	1		L
Inspected by: Roger King Date: 24 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: