



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,532,858
Version:	1
Created:	05 Jul 2019

Make:	Honda	Body Style:	SUV
Model:	CR-V	VIN:	7AT08G7HX19301626
Year:	2010	Odometer:	103,655 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	✓	Cooling System			78	Under Carriage	Good	Exterior		
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation		•		
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good			
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good			
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	Wheels and Tyres			85	R/H Mirror	Good
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	3	86	L/H Mirror	Good			
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	3	87	L/F Guard	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	3	88	R/F Guard	Good			
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	3	89	L/H Doors	Good			
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	90	R/H Doors	Good			
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	•	43	Replaced at (odometer reading)		Interior			92	R/H Sill	Good			
15	Number Plate Light	✓	Brakes			67	AC Operation	✓	93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	94	Front Bumper	Good			
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	95	Rear Bumper	Good			
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	96	Roof	Good			
19	Rev Counter	✓	Keys and Locking			71	Seat Heaters	•	97	Bonnet	Good			
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	98	Fuel Cap		✓		
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps		✓		
22	Window Opener FL	✓	49	Number of Keys	1	74	Seats	Average	100	WOF		✓		
23	Window Opener FR	✓	Engine			75	Carpets	Good	Turners Certification Key: ✓ = Pass ✗ = Fail • = Not applicable for this vehicle					
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Good						
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Good						
26	Rear View Mirrors	✓	52	Performance	✓									
27	Radio (Basic Test Only)	✓	53	Noise	✓									
28	CD (Basic Test Only)	✓	54	Starter Motor	✓									
29	Boot Open Switch	✓												

Inspected by:	John Lindsay	Date:	05 Jul 2019
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--