



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,533,085
Version:	1
Created:	16 Jul 2019

Make:	Nissan	Body Style:	Sedan
Model:	Fuga	VIN:	7AT0DH8GX19213819
Year:	2005	Odometer:	59,744 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good				
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	5.0	mm	86	L/H Mirror	Good					
7	Rear Right Indicators	✓	37	CV Joints	•	62	Right Front	5.5	mm	87	L/F Guard	Good					
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	5.0	mm	88	R/F Guard	Good					
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	5.5	mm	89	L/H Doors	Good					
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	Yes	66	Tools	✓	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain					Interior		91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable					92	R/H Sill	Good					
13	Dashboard Lights	✓	43	Replaced at (odometer reading)						93	Boot/Tail Gate	Good					
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th>	67	AC Operation	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>	94	Front Bumper	Good				
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	46	Handbrake	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	68	Heater Fan	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good			
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td>96</td><td>Roof</td><td>Good</td></th></th>	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>	70	Horn	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>71</td> <td>Seat Heaters</td> <th>✓<td>72</td><td>Sun Visors</td><th>✓<td>97</td><td>Bonnet</td><td>Good</td></th></th>	49	Number of Keys	1	71	Seat Heaters	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td></th>	72	Sun Visors	✓ <td>97</td> <td>Bonnet</td> <td>Good</td>	97	Bonnet	Good
18	Odometer	✓	49	Number of Keys	1	Engine		73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	74	Seats	Good	98	Fuel Cap	✓	
19	Rev Counter	✓	50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td><td>99</td><td>Mud Flaps</td><th>✓</th></th>	51	Smokes and Fumes	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	75	Carpets	Good	76	Panels	Good	99	Mud Flaps	✓
20	Fuel Gauge	✓	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>77</td><td>Dashboard</td><td>Good</td><td>78</td><td>Under Carriage</td><td>Good</td><td>100</td><td>WOF</td><th>✓</th></th>	53	Noise	✓ <td>77</td> <td>Dashboard</td> <td>Good</td> <td>78</td> <td>Under Carriage</td> <td>Good</td> <td>100</td> <td>WOF</td> <th>✓</th>	77	Dashboard	Good	78	Under Carriage	Good	100	WOF	✓
21	Wipers Front/Rear	✓	54	Starter Motor	✓ <td colspan="10"></td>												
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Sudhin Ramachandran	Date:	26 Jun 2019
I have read and understood this condition guide:			
Name:		Signature:	