

Report ID: 19,534,598 Version: 1 26 Jun 2019 Created:

Make:	Suzuki	Model:	Grand Vitara	Body Style:	SUV		Pass	Fail	N/A
Year:	2009	Registration:	FFH903	Reg Expiry:	06 Nov 2019	Engine		L	
WoF Expiry:	17 May 2020	Odometer:	114,792 Kms	Good No:	19534598	Oil level	~		
VIN:	JSAJTA74V00500541	Next Service:	124000	Service Histor	y: No	Smoke & fumes	~		1
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC				S SC	Performance	~		
Key:	La C	$-\infty$		5(0)-	330	Radiator / Hoses (visual)	~		
S = scratch D = dent	TE				Tan	Transmission	1		4
D = dent R = rust	sc			710	HIVS	Operation	~		
PT = paint defe	ect NP			$\left[\left(\right) \right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	~		
P = pin dent	HIG				거네	CV joints	~		-
* = decals	sc 6/6			-No-	ALD S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC SC						Performance	~		
Dadular		Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		+
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed trea	d depth	of tyre	L es)
						Left front 5 mm			
						Right front			mm
						Left rear			mm
Conditions During Body Inspection, D.						Right rear		3 n 3 n	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	162		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		-
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		T
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FE	~ ~		
General C	Comments					Window winder RL	-		~
						Window winder RL Window winder RR			
						Rear view mirrors	~		~
									──
						Radio (basic test only)	v		──
						CD (basic test only) Number of keys			<u> </u>
			_			,	1		T
Road Con	ditions During Tes	t Drive:	Dry			Central locking	v		<u> </u>
Engine Tir	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Donovan Matara Date: 26 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: