

Report ID: 19,534,925 Version: 1 27 Jun 2019 Created:

Make:	Toyota	Model:	Estima	Body Style:	People Mover		Pass	Fail	N/A
Year:	2007	Registration:	MBL907	Reg Expiry:	23 Mar 2020	Engine			
WoF Expiry:	09 Nov 2019	Odometer:	85,159 Kms	Good No:	19534925	Oil level	~		
VIN:	7AT0H61YX14006080	Next Service:	88439	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	W		S SSC		S SC	Performance	V		
Key:		-0	S SC		SSC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~	~	
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres			es)
RR and RL tyre edge crack Front headlamps dull									mm
						Right front	-		 mm
						Left rear			mm
Conditions During Rody Inspection: Wet						Right rear	4.5 mm		-
Conditions During Body Inspection: Wet									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Front wheel drive						Suspension performance	~		
Rear trail arm bush crack (both sides) Minor dent on front subframe						Steering performance		~	
						Shock absorbers	~	~	
						Air Conditioning / Heater	V		
Interior Comments						Operation Electrical / Accessories			
Ανατοσο									
Seats						3	~		
Carpets	Good					Tail lights Indicators	~		
	Average						~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments Steering knocking noise						Window winder RL	~		
	nera need to reposition					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
Road Conditions During Test Drive: Dry						Number of keys	1		
Road Con	Central locking	~							
Engine Timing Mechanism: Timing Chain Remote locking							~		
						Sat. Nav. (basic test only)			~
Evidence		ement: N	lot Applicable	NIII5;		Reversing camera	~		
Inspected by: Sudhin Ramachandran Date: 27 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: