# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|---|---|
| Report ID: | 19,535,484 |
| Version: | 1 |
| Created: | 27 Jun 2019 |

| | | | |
|---|---|---|---|
| Make: | Toyota | Body Style: | SUV |
| Model: | Caldina | VIN: | 7AT0H624X19028992 |
| Year: | 2006 | Odometer: | 99,307 Kms |
| Road Conditions During Test Drive: | Dry | | |

| | Electrical | |
|---|---|---|
| 1 | Battery | ✓ |
| 2 | Headlights | ✓ |
| 3 | Tail Lights | ✓ |
| 4 | High Stop Light | ✓ |
| 5 | Front Right Indicators | ✓ |
| 6 | Front Left Indicators | ✓ |
| 7 | Rear Right Indicators | ✓ |
| 8 | Rear Left Indicators | ✓ |
| 9 | Reversing Lights | ✓ |
| 10 | Rear Reflectors | ✓ |
| 11 | Hazard Lights | ✓ |
| 12 | Courtesy Lights | ✓ |
| 13 | Dashboard Lights | ✓ |
| 14 | Dashboard Dimmer Switch | • |
| 15 | Number Plate Light | ✓ |
| 16 | Dashboard Warning Lights | ✓ |
| 17 | Speedo | ✓ |
| 18 | Odometer | ✓ |
| 19 | Rev Counter | ✓ |
| 20 | Fuel Gauge | ✓ |
| 21 | Wipers Front/Rear | ✓ |
| 22 | Window Opener FL | ✓ |
| 23 | Window Opener FR | ✓ |
| 24 | Window Opener RL | ✓ |
| 25 | Window Opener RR | ✓ |
| 26 | Rear View Mirrors | ✓ |
| 27 | Radio (Basic Test Only) | ✓ |
| 28 | CD (Basic Test Only) | ✓ |
| 29 | Boot Open Switch | ✓ |
| 30 | Fuel Flap Release | ✓ |
| 31 | Reversing Camera | ✓ |
| 32 | USB Port | • |
| 33 | Window Lock Switch | ✓ |
| | **Transmission and Drive** | |
| 34 | Operation | ✓ |
| 35 | Noise | ✓ |
| 36 | Clutch | • |
| 37 | CV Joints | ✓ |
| 38 | Wheel Bearing | ✓ |
| 39 | Wheel Balance | ✓ |
| 40 | Gearbox (Manual) | • |
| 41 | Engine Timing | Timing Chain |
| 42 | Evidence of Cam Belt Replacement | Not Applicable |
| 43 | Replaced at (odometer reading) | |
| | **Brakes** | |
| 44 | Front Brakes | ✓ |
| 45 | Rear Brakes | ✓ |
| 46 | Handbrake | ✓ |
| | **Keys and Locking** | |
| 47 | Central Locking | ✓ |
| 48 | Remote Locking | ✓ |
| 49 | Number of Keys | 2 |
| | **Engine** | |
| 50 | Oil Level | ✓ |
| 51 | Smokes and Fumes | ✓ |
| 52 | Performance | ✓ |
| 53 | Noise | ✓ |
| 54 | Starter Motor | ✓ |
| | **Cooling System** | |
| 55 | Coolant Condition | ✓ |
| 56 | Performance | ✓ |
| 57 | Radiator/Hoses (visual) | ✓ |
| | **Suspension** | |
| 58 | Suspension Performance | ✓ |
| 59 | Steering Performance | ✓ |
| 60 | Shock Absorbers | ✓ |
| | **Wheels and Tyres** | |
| 61 | Left Front | 4 |
| 62 | Right Front | 4 |
| 63 | Left Rear | 7 |
| 64 | Right Rear | 7 |
| 65 | Spare | Yes |
| 66 | Tools | ✓ |
| | **Interior** | |
| 67 | AC Operation | ✓ |
| 68 | Heater Fan | ✓ |
| 69 | Seatbelts | ✓ |
| 70 | Horn | ✓ |
| 71 | Seat Heaters | • |
| 72 | Sun Visors | ✓ |
| 73 | Sun Visors Lights/Mirrors | ✓ |
| 74 | Seats | Good |
| 75 | Carpets | Good |
| 76 | Panels | Good |
| 77 | Dashboard | Good |

| | Exterior | |
|---|---|---|
| 78 | Under Carriage | Good |
| 79 | Sun Roof Operation | • |
| 80 | Front Windscreen (no chips) | Good |
| 81 | Back Windscreen (no chips) | Good |
| 82 | Side Windows (no chips) | Good |
| 83 | Front Wiper Blades | Good |
| 84 | Rear Wiper Blade | Good |
| 85 | R/H Mirror | Good |
| 86 | L/H Mirror | Good |
| 87 | L/F Guard | Good |
| 88 | R/F Guard | Good |
| 89 | L/H Doors | Good |
| 90 | R/H Doors | Good |
| 91 | L/H Sill | Good |
| 92 | R/H Sill | Good |
| 93 | Boot/Tail Gate | Good |
| 94 | Front Bumper | Good |
| 95 | Rear Bumper | Good |
| 96 | Roof | Good |
| 97 | Bonnet | Good |
| 98 | Fuel Cap | ✓ |
| 99 | Mud Flaps | ✓ |
| 100 | WOF | ✓ |

**Turners Certification Key:**

✓ = Pass

✕ = Fail

• = Not applicable for this vehicle

| | | | |
|---|---|---|---|
| Inspected by: | John Lindsay | Date: | 27 Jun 2019 |

**I have read and understood this condition guide:**

| | | | |
|---|---|---|---|
| Name: | | Signature: | |