



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,536,645
Version:	1
Created:	02 Jul 2019

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	VIN:	7AT0GF1RX19020962
Year:	2012	Odometer:	82,370 Kms
Road Conditions During Test Drive:	Wet		

Electrical			30	Fuel Flap Release	✓	Cooling System			78	Under Carriage	Good	Exterior		
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation	•			
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good			
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good			
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	85	R/H Mirror	Good			
8	Rear Left Indicators	✓	37	CV Joints	✓	Wheels and Tyres			86	L/H Mirror	Good			
9	Reversing Lights	✓	38	Wheel Bearing	✓	61	Left Front	4	87	L/F Guard	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓	62	Right Front	4	88	R/F Guard	Good			
11	Hazard Lights	✓	40	Gearbox (Manual)	✓	63	Left Rear	4	89	L/H Doors	Good			
12	Courtesy Lights	✓	41	Engine Timing	Cambelt	64	Right Rear	4	90	R/H Doors	Good			
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	No	65	Spare	Yes	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		66	Tools	✓	92	R/H Sill	Good			
15	Number Plate Light	✓	Brakes			Interior			93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	67	AC Operation	✓	94	Front Bumper	Good			
17	Speedo	✓	45	Rear Brakes	✓	68	Heater Fan	✓	95	Rear Bumper	Good			
18	Odometer	✓	46	Handbrake	✓	69	Seatbelts	✓	96	Roof	Good			
19	Rev Counter	✓	Keys and Locking			70	Horn	✓	97	Bonnet	Good			
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	98	Fuel Cap	✓			
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	99	Mud Flaps	✓			
22	Window Opener FL	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓	100	WOF	✓			
23	Window Opener FR	✓	Engine			74	Seats	Good						
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good						
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Good						
26	Rear View Mirrors	✓	52	Performance	✓	77	Dashboard	Good						
27	Radio (Basic Test Only)	✓	53	Noise	✓									
28	CD (Basic Test Only)	✓	54	Starter Motor	✓									
29	Boot Open Switch	✓												

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:
 ✓ = Pass
 ✗ = Fail
 • = Not applicable for this vehicle

Inspected by:	Xinghui Lin	Date:	02 Jul 2019
I have read and understood this condition guide:			
Name:		Signature:	