

Report ID: 19,537,563 Version: 2 05 Aug 2019 Created:

Make:	Hyundai	Model:	120	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2012	Registration:	LTW568	Reg Expiry:	25 Oct 2019	Engine	1	<u> </u>		
WoF Expiry:	29 Jul 2020	Odometer:	66,130 Kms	Good No:	19537563	Oil level	~			
VIN:	MALBB51CMDM4371	Next Service:	68,000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
			*			Performance	~			
Key:		-0	* <u>s</u>			Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust	S PT			715	S PT	Operation	~			
PT = paint defe	ect NP			$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				74114	CV joints	~			
* = decals	sc 916			The second		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
			*			Performance	~			
Body Incr	portion Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments Key buttons torn						Tyres (lowest observed tread	d depth	of tyre	es)	
									mm	
						Right front	3	3	mm	
						Left rear	e		mm	
Conditions During Body Inspection: Dry						Right rear	6 mr		mm	
Conditions During Dody inspection. Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Front whee	el drive					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Average					Tail lights	~			
Carpets	/ verage					Indicators	~			
Panels	Good					Dashboard warning lights	~			
	. Good					Wipers (front & rear)	~			
Dashboa	ard					Window winder FL	~			
	•				· · · · · · · · · · · · · · · · · · ·	Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
			•			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
·										
Inspected by: Mathew Varghese Date: 05 Aug 2019										

I have read and understood this condition guide.

Name:

Signature: