



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

|            |             |
|------------|-------------|
| Report ID: | 19,539,135  |
| Version:   | 4           |
| Created:   | 01 Aug 2019 |

|                                    |         |             |                   |
|------------------------------------|---------|-------------|-------------------|
| Make:                              | Subaru  | Body Style: | Hatchback         |
| Model:                             | Impreza | VIN:        | 7AT0GF09X19037953 |
| Year:                              | 2010    | Odometer:   | 103,692 Kms       |
| Road Conditions During Test Drive: | Dry     |             |                   |

| Electrical |                          |   | 30                     | Fuel Flap Release                | ✓       | Cooling System |                           |         | 78               | Under Carriage              | Good | Exterior |  |
|------------|--------------------------|---|------------------------|----------------------------------|---------|----------------|---------------------------|---------|------------------|-----------------------------|------|----------|--|
| 1          | Battery                  | ✓ | 31                     | Reversing Camera                 | •       | 55             | Coolant Condition         | ✓       | 79               | Sun Roof Operation          | •    |          |  |
| 2          | Headlights               | ✓ | 32                     | USB Port                         | •       | 56             | Performance               | ✓       | 80               | Front Windscreen (no chips) | Good |          |  |
| 3          | Tail Lights              | ✓ | 33                     | Window Lock Switch               | ✓       | 57             | Radiator/Hoses (visual)   | ✓       | 81               | Back Windscreen (no chips)  | Good |          |  |
| 4          | High Stop Light          | ✓ | Transmission and Drive |                                  |         | Suspension     |                           |         | 82               | Side Windows (no chips)     | Good |          |  |
| 5          | Front Right Indicators   | ✓ | 34                     | Operation                        | ✓       | 58             | Suspension Performance    | ✓       | 83               | Front Wiper Blades          | Good |          |  |
| 6          | Front Left Indicators    | ✓ | 35                     | Noise                            | ✓       | 59             | Steering Performance      | ✓       | 84               | Rear Wiper Blade            | Good |          |  |
| 7          | Rear Right Indicators    | ✓ | 36                     | Clutch                           | •       | 60             | Shock Absorbers           | ✓       | Wheels and Tyres |                             |      |          |  |
| 8          | Rear Left Indicators     | ✓ | 37                     | CV Joints                        | ✓       | 61             | Left Front                | 4.0 mm  | 85               | R/H Mirror                  | Good |          |  |
| 9          | Reversing Lights         | ✓ | 38                     | Wheel Bearing                    | ✓       | 62             | Right Front               | 5.0 mm  | 86               | L/H Mirror                  | Good |          |  |
| 10         | Rear Reflectors          | ✓ | 39                     | Wheel Balance                    | ✓       | 63             | Left Rear                 | 4.0 mm  | 87               | L/F Guard                   | Good |          |  |
| 11         | Hazard Lights            | ✓ | 40                     | Gearbox (Manual)                 | •       | 64             | Right Rear                | 4.0 mm  | 88               | R/F Guard                   | Good |          |  |
| 12         | Courtesy Lights          | ✓ | 41                     | Engine Timing                    | Cambelt | 65             | Spare                     | Yes     | 89               | L/H Doors                   | Good |          |  |
| 13         | Dashboard Lights         | ✓ | 42                     | Evidence of Cam Belt Replacement | No      | 66             | Tools                     | ✓       | 90               | R/H Doors                   | Good |          |  |
| 14         | Dashboard Dimmer Switch  | ✓ | 43                     | Replaced at (odometer reading)   |         | Interior       |                           |         | 91               | L/H Sill                    | Good |          |  |
| 15         | Number Plate Light       | ✓ | Brakes                 |                                  |         | 67             | AC Operation              | ✓       | 92               | R/H Sill                    | Good |          |  |
| 16         | Dashboard Warning Lights | ✓ | 44                     | Front Brakes                     | ✓       | 68             | Heater Fan                | ✓       | 93               | Boot/Tail Gate              | Good |          |  |
| 17         | Speedo                   | ✓ | 45                     | Rear Brakes                      | ✓       | 69             | Seatbelts                 | ✓       | 94               | Front Bumper                | Good |          |  |
| 18         | Odometer                 | ✓ | 46                     | Handbrake                        | ✓       | 70             | Horn                      | ✓       | 95               | Rear Bumper                 | Good |          |  |
| 19         | Rev Counter              | ✓ | Keys and Locking       |                                  |         | 71             | Seat Heaters              | •       | 96               | Roof                        | Good |          |  |
| 20         | Fuel Gauge               | ✓ | 47                     | Central Locking                  | ✓       | 72             | Sun Visors                | ✓       | 97               | Bonnet                      | Good |          |  |
| 21         | Wipers Front/Rear        | ✓ | 48                     | Remote Locking                   | ✓       | 73             | Sun Visors Lights/Mirrors | ✓       | 98               | Fuel Cap                    | ✓    |          |  |
| 22         | Window Opener FL         | ✓ | 49                     | Number of Keys                   | 2       | 74             | Seats                     | Average | 99               | Mud Flaps                   | ✓    |          |  |
| 23         | Window Opener FR         | ✓ | Engine                 |                                  |         | 75             | Carpets                   | Average | 100              | WOF                         | ✓    |          |  |
| 24         | Window Opener RL         | ✓ | 50                     | Oil Level                        | ✓       | 76             | Panels                    | Good    |                  |                             |      |          |  |
| 25         | Window Opener RR         | ✓ | 51                     | Smokes and Fumes                 | ✓       | 77             | Dashboard                 | Good    |                  |                             |      |          |  |
| 26         | Rear View Mirrors        | ✓ | 52                     | Performance                      | ✓       |                |                           |         |                  |                             |      |          |  |
| 27         | Radio (Basic Test Only)  | • | 53                     | Noise                            | ✓       |                |                           |         |                  |                             |      |          |  |
| 28         | CD (Basic Test Only)     | • | 54                     | Starter Motor                    | ✓       |                |                           |         |                  |                             |      |          |  |
| 29         | Boot Open Switch         | ✓ |                        |                                  |         |                |                           |         |                  |                             |      |          |  |

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

|               |                  |       |             |
|---------------|------------------|-------|-------------|
| Inspected by: | Kyle Mills-Brown | Date: | 02 Jul 2019 |
|---------------|------------------|-------|-------------|

**I have read and understood this condition guide:**

|       |  |            |  |
|-------|--|------------|--|
| Name: |  | Signature: |  |
|-------|--|------------|--|