

Report ID: 19,539,399 Version: 1 02 Jul 2019 Created:

| Make: | Suzuki | Model: | SX4 | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|------------------------|----------------------|------------------------|-----------------|----------------------|--|-------|------|-----|
| Year: | 2012 | Registration: | GFY154 | Reg Expiry: | 06 Feb 2020 | Engine | | | L |
| WoF Expiry: | 18 Apr 2020 | Odometer: | 146,265 Kms | Good No: | 19539399 | Oil level | ~ | | |
| VIN: | JSAGYB51S00310025 | Next Service: | 145,000kms | Service History | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismontled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | ~ | | |
| | S | | SD* S | | S SC | Performance | ~ | | |
| Key: | <u> </u> | -0 | | | 330 | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| B = rust SC A A SPT | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | |
| " = decais | | | | | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Cargo barrier in rear seats | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Front bumper fog light cover missing x1 | | | | | | Left front | 5 mm | | mm |
| Remote key fail Rear windscreen sprayer fail | | | | | | Right front | 5. | .5 | mm |
| | | | | | | Left rear | 4.5 m | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6 mm | | mm |
| | | | | | Spare | Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| AWD | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | Shock absorbers | ~ | | | | | | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Comoto | Floor mate | missing | | | | Tail lights | ~ | | |
| Carpets | | - | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | < | | |
| Dashboa | iu l | | | | | Window winder FL | ~ | | |
| | - | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | 1 | | |
| | | | | | | Window winder RR | < | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | | 1 | | |
| Remote locking | | | | | | | | ~ | |
| Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only) | | | | | | | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Ca Thach Date: 02 Jul 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: