

Basic Vehicle Condition Guide

Report ID: 19,539,458


Version: 2

Created: 12 Jul 2019

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2015 Registration: JFC823 Reg Expiry: 16 Oct 2019 Good No: WoF Expiry: **Odometer:** 05 Jul 2020 160,675 Kms 19539458 VIN: KMHST81XSFU494927 Next Service: 170000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------------------------------|--|--|
| Seats | wear and tear,minor stains , | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Please note: Front brake pads getting low but has passed WOF

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Date: 11 Jul 2019 Inspected by: Donovan Matara

Name:

| | Pass | Fail | N/A | |
|------------------------------|--|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | V V | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | <i>v v</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 5 | .0 | mm | |
| Right front | 5 | .0 | mm | |
| Left rear | 3 | .0 | mm | |
| Right rear | 3.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | \(\times \) \(\t | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | | | | |
| Window winder RL | ~ | | | |
| Window winder RR | \(\times \) | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | 1 | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ' | | | |
| | | | | |

Signature: