

Report ID: 19,540,313 Version: 2 15 Jul 2019 Created:

| Make: | Nissan | Model: | Tiida | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|------------------|----------------------------|--------------------|----------------------|---|--------|----------|--------|
| Year: | 2005 | Registration: | | Reg Expiry: | 06 Oct 2019 | Engine | I | <u> </u> | |
| WoF Expiry: | 14 Oct 2019 | Odometer: | 123,816 Kms | Good No: | 19540313 | Oil level | ~ | | |
| VIN: | 7AT0DH78X12037737 | Next Service: | | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is maala | for one and miles as | Danta hava nat | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | L | -0 | SP S | | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | s 6/6 | | | 10 | EID S | Operation | ~ | | |
| R = rust PT = paint defe | | | | \prod | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIC | | | | | CV joints | ~ | | • |
| * = decals | s PIK | | | - AL | EITR | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S W SP SP W | | | | | | Performance | ~ | | |
| | | Note: som | ne defects & blemishes | may not be disr | laved in the diagram | Hand Brake | ~ | | |
| | pection Comments | 1 | | | , , | | • | oftyre |)) |
| Scratch mark front screen n Drivers door mirror. Right hand head light lens dirty. Wet in spare well. | | | | | | Tyres (lowest observed tread depth of tyres) Left front 4 | | | |
| | | | | | | Right front | | | mm |
| | | | | | | Left rear | | | mm |
| | | | | | | | 6 | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6.5 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| FWD. | inage a onder bor | incernspectie | comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Good n Drivers sign of wear | | | | | | Electrical / Accessories | | | 1 |
| Seats | | | | | | Head lights | ~ | | |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | Good | | | | | Indicators | ~ | | |
| Panels | | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| Ganaral | omments | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> Drivers door window sometimes slow to operate.Slight fan belt noise on start up.Engine oil level on low | | | | | | Window winder RL | ~ | | |
| | steering knock at low s | | .g. a fair bere holse offs | ant aplengine o | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Tes | t Drive: | Dry | | | Central locking | ~ | | |
| | ning Mashering | T: | Choin | |] | Remote locking | ~ | | |
| - | ming Mechanism: | Timing (| | 17 | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| lunar | | | | | | Date: 15 1.1001 | 0 | | |
| Inspected | d by: Eddie Marsters | | | | | Date: 15 Jul 201 | J | | |

I have read and understood this condition guide.

Name:

Signature: