

Basic Vehicle Condition Guide

Report ID: 19,540,711


Version: 1

Created: 30 Jul 2019

Make: Model: Mazda Axela **Body Style:** Hatchback Year: 2008 Registration: **GQM794** Reg Expiry: 09 Jun 2020 WoF Expiry: **Odometer:** 02 Aug 2020 196,796 Kms **Good No:** 19540711 VIN: 7AT0C13JX12320558 **Next Service:** 206315 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 02 Jul 2019

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	V V			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	\(\triangle \)			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes		ı		
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front	4	.0	mm	
Right front	4	.0	mm	
Left rear		3	mm	
Right rear	3		mm	
Spare		Yes		
Suspension		ı		
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	<i>\</i>			
Tail lights	<i>'</i>			
Indicators	<i>V</i>			
Dashboard warning lights	•			
Wipers (front & rear)	> > > > > > > > > > > > > > > > > > >			
Window winder FL	•			
Window winder FR				
Window winder RL	-			
Window winder RR	-			
Rear view mirrors	\(\times \)			
Radio (basic test only)				
CD (basic test only)	2			
Number of keys	2			
Central locking Remote locking	•			
			.,	
Sat. Nav. (basic test only)			"	
Reversing camera				

Signature: