

Report ID: 19,541,037 Version: 2 19 Jul 2019 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2002	Registration:	BEJ134	Reg Expiry:	11 Feb 2019	Engine				
WoF Expiry:	18 Jul 2020	Odometer:	140,151 Kms	Good No:	19541037	Oil level	~			
VIN:	6G1YK54F43L924819	Next Service:	130000	Service Histor	y: No	Smoke & fumes	r			
						Performance	r			
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise		~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
		_				Performance	~			
Key:						Radiator / Hoses (visual)	~			
S = scratch						Transmission				
						Operation 🖌				
R = rust PT = paint defect						Noise	~			
C = crack						Clutch	•		~	
P = pin dent	Ho					CV joints			~	
*=decals SC 919						Wheel bearings	~		•	
SC = stone chips						Brakes	5			
W = significant scuffs						Performance	~			
		Note: com			laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture		
Water inside boot(need further investigation)						Tyres (lowest observed tread depth of tyres)				
						Left front	4		mm	
						Right front		1	mm	
						Left rear		7	mm	
Conditions During Body Inspection: Dry						Right rear			mm	
Under Corriges & Under Despecting Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments After market mag and suspension parts fitted Oil leak in engine and transmission area						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior C	o ma un o mato					Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpets	Average					Tail lights	~			
						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Good					Wipers (front & rear)	~			
Dashboa	iu					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
Engine/fan belt noisy when cold start 2wd						Window winder RR	~			
One remote key worn						Rear view mirrors	~			
CD rom not	working					Radio (basic test only)	~			
						CD (basic test only)		~		
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
	-					Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected by: Bobby Zhong Date: 19 Jul 2019										

I have read and understood this condition guide.

Name:

Signature: