

Basic Vehicle Condition Guide

Report ID: 19,541,156

Version: 3


Created: 03 Jul 2019

Pass Fail N/A

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2014 Registration: HHR345 Reg Expiry: 16 Jul 2020 **Odometer:** WoF Expiry: 22 Mar 2020 150,911 Kms **Good No:** 19541156 VIN: MR0GZ12G30900127: Next Service: 165000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Holes on the roof

Stone chips on the windscreen

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive

Underbody radiator support frame rust

Engine mount weak

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Name:

			1
Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System		•	•
Coolant condition	ン ン ン		
Performance	>		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	V		
Clutch	>		
CV joints			~
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	/		
Tyres (lowest observed tread	l deptl	of tyre	es)
Left front	6	i.5	mm
Right front	6.5		mm
Left rear	7.5 mm		
Right rear	7.5 mm		
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	> > > >		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3	,	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			V

Reversing camera

03 Jul 2019

Signature:

Inspected by:	Sudhin Ramachandran