

Report ID: 19,541,457 Version: 3 18 Jul 2019 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A
Year:	2015	Registration:	JFE902	Reg Expiry:	29 Sep 2019	Engine			1
	17 Jul 2020	Odometer:	70,022 Kms	Good No:	19541457	Oil level	~		
VIN:	KMHE241FMFA08913	Next Service:	78000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	S S		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	•		~
P = pin dent						CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	he defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	 >s)
RR taillight lense broken FL door frame dent									
						Right front			mm
						Left rear	6		mm
							5.		
Conditions During Body Inspection: Wet						Right rear	6.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Front wheel drive						Suspension			1
FIOID WHEE	runve					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats	, it cluge					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concert						Window winder FR	~		
General Comments One remote manual key spring damage						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
Road Conditions During Test Drive: Wet						CD (basic test only)	~		
						Number of keys	2	_	
						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Sudhin Ramachandran							0		
Inspected by: Sudhin Ramachandran Date: 18 Jul 2019									
I have read and understood this condition guide. Name:									