

Basic Vehicle Condition Guide

Report ID: 19,541,796


Version: 1

Created: 30 Jul 2019

Make: Model: Suzuki **Grand Vitara Body Style:** SUV Year: 2016 Registration: JTJ715 Reg Expiry: 27 Oct 2019 WoF Expiry: **Odometer: Good No:** 28 Mar 2020 65,878 Kms 19541796 VIN: **Next Service:** JSAJTEA4V00350125 80000 km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eddie Marsters Date: 30 Jul 2019

Name:

	Pass	Fail	N/A
Engine		•	
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	8	8	mm
Right front		8	mm
Left rear		8	mm
Right rear		8	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	V		
Radio (basic test only)	~		
CD (basic test only)	~		
CD (basic test only) Number of keys	1		
<u> </u>	1		
Number of keys	1		
Number of keys Central locking	1		

Signature: