

Basic Vehicle Condition Guide

Report ID: 19,541,834


Version: 2

Created: 26 Jul 2019

Make: Model: KIA Sportage **Body Style:** SUV Year: 2011 Registration: GDU83 Reg Expiry: 28 Nov 2019 WoF Expiry: **Odometer:** 08 Aug 2020 175,760 Kms **Good No:** 19541834 VIN: KNAPB811MC722921(Next Service: 184240 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

One remote key button cover broken and not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

26 Jul 2019 Inspected by: **Bobby Zhong**

Name:

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|-----|
| Engine | • | • | • |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | • | |
| Coolant condition | ~ | | |
| Performance | V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 4 | 4 | mm |
| Right front | 3 | | mm |
| Left rear | Left rear 2 | | mm |
| Right rear | 3 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | • | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | V V V V V V V V V V V V V V V V V V V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Canatanal I a alidas as | T | | |
| Central locking | | | |
| Remote locking | \(\triangle \) | | |
| | \(\triangle \) | | ~ |

Signature: