

Report ID: 19,541,997 Version: 2 01 Oct 2019 Created:

Make:	Honda	Model:	Stream	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007		LDD727	Reg Expiry:	02 Oct 2019	Engine			L
WoF Expiry:		Odometer:	167,264 Kms	Good No:	19541997	Oil level	~		
VIN:	7AT08GADX17037755	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The		Operation	~		
R = rust PT = paint def				í In	JHH	Noise	~		
C = crack						Clutch			~
P = pin dent					ᅰЦ	CV joints	~		
* = decals	616			- NL	ELIPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	-	oftyre	
Stone chips front screen drivers.					Left front 5 mm				
						Right front		.5	mm
						Left rear	-		mm
						Right rear			-
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	,					Suspension performance	~		1
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Operation Electrical / Accessories			
Seats Good						Head lights			
Seals						Tail lights			
Carpets	Good						レ レ		
Devision	Good					Dashboard warning lights	<i>v</i> <i>v</i>		<u> </u>
Panels						Wipers (front & rear)	<i>v</i> <i>v</i>		+
Dashboa	Ird Good					Window winder FL	<i>v</i> <i>v</i>		
						Window winder FL Window winder FR			
General (<u>Comments</u>					Window winder FR	v		$\left - \right $
Unable to make CD work.Slight trans fluid leak.						Window winder RL Window winder RR	~ ~		
						Rear view mirrors	<i>v</i> <i>v</i>		
						Radio (basic test only)	~		
						CD (basic test only)	-	~	
						Number of keys	2	•	L
Road Conditions During Test Drive: Dry						Central locking			
Koad Con	aitions During Test	Drive:	Dry			Remote locking	~ ~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	•		
-	of Cam Belt Replac	_	lot Applicable	Kms:		Reversing camera			v
									~
Inspected by: Roger King Date: 01 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: