

## Turners Certified 100 Point Check

## Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Version: 1 Created: 05 Jul 2019	Report ID:	19,542,292
Created: 05 Jul 2019	Version:	1
	Created:	05 Jul 2019

Make:	Nissan	Body Style:	Van
Model:	NV200	VIN:	7AT0DH8MX19016040
Year:	2011	Odometer:	68,629 Kms
Road Conditions During Test Drive:	Dry		

Ele	ctrical	30	Fuel Flap Release		Coc	oling System		Exte	erior	
1	Battery	31	Reversing Camera	•	55	Coolant Condition	on 🗹	78	Under Carriage	Good
2	Headlights	32	USB Port	•	56	Performance	V	79	Sun Roof Operation	•
3	Tail Lights	33	Window Lock Swit	tch	57	Radiator/Hoses (visual)		80	Front Windscreen (no chips)	Good
4	High Stop Light	Tra	nsmission and D	Prive	Sus	pension		81	Back Windscreen (no chips)	Good
5	Front Right Indicators	34	Operation		58	Suspension Performance		82	Side Windows (no chips)	Good
6	Front Left Indicators	35	Noise		59	Steering Performance		83	Front Wiper Blades	Good
7	Rear Right Indicators	36	Clutch	•	60	Shock Absorbers		84	Rear Wiper Blade	Good
8	Rear Left Indicators	37	CV Joints		Wh	eels and Tyres		85	R/H Mirror	Good
9	Reversing Lights	38	Wheel Bearing		61	Left Front	3	86	L/H Mirror	Good
10	Rear Reflectors	39	Wheel Balance		62	Right Front	3	87	L/F Guard	Good
11	Hazard Lights	40	Gearbox (Manual)	) •	63	Left Rear	3	88	R/F Guard	Good
12	Courtesy Lights	41	Engine Timing	Timing Chain	64	Right Rear	4	89	L/H Doors	Good
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes	90	R/H Doors	Good
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)		66	Tools		91	L/H Sill	Good
15	Number Plate Light	Bra	hkes		Inte	Interior		92	R/H Sill	Good
16	Dashboard Warning Lights	44	Front Brakes		67	AC Operation	<b>V</b>	93	Boot/Tail Gate	Good
17	Speedo	45	Rear Brakes		68	Heater Fan	<b>V</b>	94	Front Bumper	Good
18	Odometer	46	Handbrake		69	59 Seatbelts		95	Rear Bumper	Good
19	Rev Counter	Key	/s and Locking		70	Horn		96	Roof	Good
20	Fuel Gauge	47	Central Locking		71	Seat Heaters	•	97	Bonnet	Good
21	Wipers Front/Rear	48	Remote Locking		72	Sun Visors	V	98	Fuel Cap	
22	Window Opener FL	49	Number of Keys	2	73	Sun Visors Lights	s/Mirrors	99	Mud Flaps	
23	Window Opener FR	Eng	gine		74	Seats	Average	100	WOF	
24	Window Opener RL	50	Oil Level		75	Carpets	Good			
25	Window Opener RR	51	Smokes and Fume	es 🚺	76	Panels	Good			
26	Rear View Mirrors	52	Performance		77	Dashboard	Good			
27	Radio (Basic Test Only)	53	Noise					Turn	ers Certification K	(ey:
28	CD (Basic Test Only)	54	Starter Motor					✓=F X=F		
29	Boot Open Switch								lot applicable for thi	is vehicle

Inspected by:	John Lindsay	Date:	05 Jul 2019				
I have read and understood this condition guide:							
Name:		Signature:					